SPE! T. Tran

		R CERTIFICATE OF CORRECTION	_			
	2/10/10/0	Paper No.:				
DATE :	7/0/04					
TO SPE OF : ART	UNIT 2621					
SUBJECT : Requ	: Request for Certificate of Correction for Appl. No.: <u>09/615,577</u> Patent No.: <u>6993148</u>					
Please respond to	this request for a certif	ficate of correction within 7 days.				
	n image. No new matt	rrections as shown in the COCIN document(s) in er should be introduced, nor should the scope or				
Please complete the using document co		w) and forward the completed response to scanning	9			
	•	Lamonte M. Newsome Certificates of Correction Branch				
		703-308-9390 ext. <u>112</u>				
Thank You For Yo	our Assistance	703-308-9390 ext. <u>112</u>				
The request for is	ssuing the above-ider	703-308-9390 ext112				
The request for is	ssuing the above-ider	·				
The request for is Note your decision on the a	ssuing the above-ider	ntified correction(s) is hereby:				
The request for is Note your decision on the a	ssuing the above-ider ppropriate box. roved roved in Part	ntified correction(s) is hereby: All changes apply.				
The request for is Note your decision on the appr Appr Appr	ssuing the above-ider ppropriate box. roved roved in Part	All changes apply. Specify below which changes do not apply. State the reasons for denial below.				
The request for is Note your decision on the appr Appr Appr	ssuing the above-ider ppropriate box. roved roved in Part	All changes apply. Specify below which changes do not apply. State the reasons for denial below.				
The request for is Note your decision on the appr Appr	ssuing the above-ider ppropriate box. roved roved in Part	All changes apply. Specify below which changes do not apply. State the reasons for denial below.				
The request for is Note your decision on the appr Appr Appr	ssuing the above-ider ppropriate box. roved roved in Part ed lease see the	All changes apply. Specify below which changes do not apply. State the reasons for denial below. Attached Page for Comments. MATTHEW C. BELLA				
The request for is Note your decision on the appr Appr Appr	ssuing the above-ider ppropriate box. Foved Foved in Part The lease see the surface see the surface see see the surface see	All changes apply. Specify below which changes do not apply. State the reasons for denial below. Attached Page for Comments.				

- 1. Title page correction ("At Item (56)...Kurokid et al. should read - Parker et al. -.) on page 1 of certificate of correction is not approved. See the front page of U.S. Patent 5,113,310. If at all, the correction should be made from "Kurokid et al." to "Kuroki et al."
- 2. Column 1 line 37 correction ("FIG." Should read - FIGS. -") on page 1 of certificate of correction is not approved. Column 1 line 37 states "FIG. 2 or 4" which is correct.
- 3. Column 9 line 7 correction on page 1 of certificate of correction is not approved. This should refer to line 8 and not line 7.



US005113310A

United States Patent [19]

Kuroki et al.

[11] Patent Number: 5,113,310

Date of Patent:

May 12, 1992

[54]	[54] DIELECTRIC FILTER						
b		Hiroshi Kuroki; Yoshifumi Yamagata, both of Kagoshima; Youichi Yamashita, Shiga, all of Japan					
[73]	Assignee:	Kyocera Corporation, Kyoto, Japan					
[21]	Appl. No.:	590,150					
[22]	Filed:	Sep. 28, 1990					
[30]	Foreign	Application Priority Data					
Sep Dec [51] [52]	. 30, 1989 [JF . 28, 1989 [JF Int. Cl. ⁵ U.S. Cl] Japan					
[56] References Cited							
U.S. PATENT DOCUMENTS							
4	1,144,509 3/1 1,179,673 12/1 1,839,773 6/1	979 Nishikawa et al 333/204					
FOREIGN PATENT DOCUMENTS							
	0038996 11/1	981 European Pat. Off.					

0093956 11/1983 European Pat. Off. .

0208424 1/1987 European Pat. Off. .

61-292401 12/1986 Japan . 24702 2/1988 Japan .


WO88/01104	2/1988	PCT Int'l Appl
WO87/01210	2/1988	PCT Int'l Appl.
2109641	10/1982	United Kingdom .
2163606A	2/1986	United Kingdom .
2165098	4/1986	United Kingdom .
2184608	6/1987	United Kingdom .
2210225A	6/1989	United Kingdom .

Primary Examiner-Donald A. Griffin Attorney, Agent, or Firm-Spensley Horn Jubas &

ABSTRACT [57]

A dielectric filter comprises a first resonator and second resonator. Each of the resonators includes a dielectric block having a through-hole, an inner conductive layer placed on the inner surface of the through-hole, and an outer conductive layer placed on the outer surface of the dielectric blocks. The first and second resonators have a coupled hole extending transversely to the through-holes in portions of the resonator couples adjacent to each other. The dielectric filter may further include a frame made of a pair of metal plates covering said coupling hole. The pair of metal plates have legs for earthing and are affixed to the filter body, whereupon the metal plates are located, apart from each other. A method for producing a dielectric filter comprises the steps of making a filter body by connecting a first resonator and second resonator; providing a pair of lead frames incorporating a plurality of metal plates; disposing said filter body between said metal plates of the pair of lead frames; and fixing the metal plates to opposite sides of the filter body.

34 Claims, 5 Drawing Sheets



Staple Here Onlyl

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,993,148 B1

DATED

January 31, 2006

INVENTOR(S) :

Tomoyuki Miyashita, et al.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE

At Item (56), U.S. Patent Documents, "Kurokid et al." should read -- Parker et al. --.

<u>COLUMN 1</u>

Line 31, "shown as" should read --as shown--. Line 37, "FIG." should read --FIGS.--.

COLUMN 5

Line 18, "frequency-band-components" should read --frequency band components--. \

COLUMN 7

Line 5, "be" should read --the--. Line 19, "+i" should read --i--.

COLUMN 8

Line 9, "values × and y" should read --values x and y--. Line 36, "bit" should read --bit- --. 7

COLUMN 9

Line 7, "all-positions" should read --all positions--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 240776

PATENT NO. 6,993,148 B1

No. of add'i. copies @ 30¢ per page

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,993,148 B1

DATED

January 31, 2006

INVENTOR(S)

Tomoyuki Miyashita, et al.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14

Line 36, "set I₂" should read --set I₁--.

COLUMN 17

Line 29, "(a'-b')" should read --(a',-b',)--.

COLUMN 18

Line 16, "including-the" should read --including the--.

COLUMN 19

Line 17, "large-size" should read --large size--.

COLUMN 20

Line 4, dobtaining" should read -- obtained--.

Line 27, " P_{gl} " should read -- P_{gl+1} --.

COLUMN 21

Line 26, "y" should read --by--.

COLUMN 23

Line 22, "divided" should read --divided by--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,993,148 B1

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 240776

Face C' court

No. of add'l. copies @ 30¢ per page

□>

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,993,148 B1

DATED

January 31, 2006

INVENTOR(S)

Tomoyuki Miyashita, et al.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24

Line 13, "addition;" should read --addition,--.

Line 25, "Means)" should read -- Means]--.

Line 40, "(num]" should read --[num]--.

Line 55, ")" should be deleted.

COLUMN 25

Line 67, "assigned." should read --assigned).--.

COLUMN 28

Line 41, "wI" should read --wI'₁--. Line 42, "wI" should read --wI'₁--.

COLUMN 29

Line 10, "example" should read --examples--.

Line 33, "32" should read --32c2--.

Line 66, "32" should read --32c2--.

COLUMN 31

Line 17, "using-the" should read --using the--.

Line 38, "22," should read --22.--.

COLUMN 37

Line 56, "value a" should read --value α --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 240776

No. of add'l. copies @ 30¢ per page

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,993,148 B1

DATED

January 31, 2006

INVENTOR(S)

Tomoyuki Miyashita, et al.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 38

Line 6, "Inf" should read --Inf2--.

Line 8, "signal:" should read --signal.--.

COLUMN 39

Line 16, "information" should read --information; --.

Line 29, "por-" should read --posi- --.

Line 38, "information" should read --information; --. \

Line 54, "information" should read --information;--.

Line 56, "an" should read -- and --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 240776

PATENT NO. 6,993,148 B1

RUUS

No. of add'l. copies @ 30¢ per page

•

☞ ____

. (Indiana PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,993,148 B1

DATED

January 31, 2006

INVENTOR(S)

Tomoyuki Miyashita, et al.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 40

Line 4, "information" should read --information;--.
Line 19, "information" should read --information;--.
Line 36, "information" should read --information;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) DSG/lip DC_MAIN 240776

PATENT NO. 6,993,148 B1

No. of add'l. copies @ 30¢ per page

...0

☞> __

COFF

00862.021952 (862.C1952)

PATENT

JUN 23 2005 IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Shervin Nakhjavan

TOMOYUKI MIYASHITA, ET AL.

Group Art Unit: 2621

Appln. No.: 09/615,577

Patent No.: 6,993,148 B1

Filed: July 13, 2000

Issued: January 31, 2006

For: IMAGE PROCESSING APPARATUS

AND METHOD, AND STORAGE MEDIUM:

June 23, 2006

Commissioner for Patents P.O. Box 1450

Alexandria, VA 22313-1450

JUN 2 8 2006 of Correction

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

06/26/2036 SZEWDIE1 00000085 6993148 81 FC:1811 100.03 OP Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010. All correspondence should be directed to our address given below.

Respectfully submitted,

Daniel S. Glueck Attorney for Patentees Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

DSG/llp

DC_MAIN 240775v1